

Ряды предпочтительных значений сопротивления

E12	E24	E48	E96	E192
1,0	1,0	1,00	1,00	1,00
				1,01
			1,02	1,02
				1,04
			1,05	1,05
				1,06
			1,07	1,07
				1,09
			1,10	1,10
				1,11
			1,13	1,13
				1,14
			1,15	1,15
				1,17
			1,18	1,18
				1,20
			1,21	1,21
1,2	1,2		1,21	1,21
				1,23
			1,24	1,24
				1,26
			1,27	1,27
				1,29
			1,30	1,30
				1,32
			1,33	1,33
				1,35
			1,37	1,37
				1,38
	1,3		1,40	1,40
				1,42
			1,43	1,43
				1,45
			1,47	1,47
				1,49
			1,50	1,50
				1,52
			1,54	1,54
				1,56
			1,58	1,58
				1,60
1,5	1,5		1,62	1,62
				1,64
			1,65	1,65
				1,67
			1,69	1,69
				1,72
			1,74	1,74
				1,76
			1,78	1,78
				1,80
	1,6		1,82	1,82
				1,84
			1,87	1,87
				1,89
			1,91	1,91
				1,93
			1,96	1,96
				1,98
			2,00	2,00
				2,03
			2,05	2,05
				2,08
1,8	2,0		2,10	2,10
				2,13
			2,15	2,15
				2,18
	2,2		2,21	2,21
				2,23

E12	E24	E48	E96	E192
2,2			2,26	2,26
				2,29
			2,32	2,32
				2,34
			2,37	2,37
				2,40
	2,4		2,43	2,43
				2,46
			2,49	2,49
				2,52
			2,55	2,55
				2,58
			2,61	2,61
				2,64
			2,67	2,67
				2,71
	2,7		2,74	2,74
				2,77
			2,80	2,80
				2,84
			2,87	2,87
				2,91
			2,94	2,94
				2,98
2,7	3,0		3,01	3,01
				3,05
			3,09	3,09
				3,12
			3,16	3,16
				3,20
			3,24	3,24
				3,28
	3,3		3,32	3,32
				3,36
			3,40	3,40
				3,44
			3,48	3,48
				3,52
			3,57	3,57
				3,61
	3,6		3,65	3,65
				3,70
			3,74	3,74
				3,79
			3,83	3,83
				3,88
			3,92	3,92
				3,97
3,3	3,9		4,02	4,02
				4,07
			4,12	4,12
				4,17
			4,22	4,22
				4,27
	4,3		4,32	4,32
				4,37
			4,42	4,42
				4,48
			4,53	4,53
				4,59
			4,64	4,64
				4,70
	4,7		4,75	4,75

E12	E24	E48	E96	E192
5,1				4,81
			4,87	4,87
				4,93
			4,99	4,99
				5,05
	5,6		5,11	5,11
				5,17
			5,23	5,23
				5,30
			5,36	5,36
				5,42
			5,49	5,49
				5,56
	6,2		5,62	5,62
				5,69
			5,76	5,76
				5,83
			5,90	5,90
				5,97
			6,04	6,04
				6,12
			6,19	6,19
				6,26
5,6	6,8		6,34	6,34
				6,42
			6,49	6,49
				6,57
			6,65	6,65
				6,73
	7,5		6,81	6,81
				6,90
			6,98	6,98
				7,06
			7,15	7,15
				7,23
			7,32	7,32
				7,41
			7,50	7,50
				7,59
			7,68	7,68
				7,77
6,2	8,2		7,87	7,87
				7,96
			8,06	8,06
				8,16
	9,1		8,25	8,25
				8,35
			8,45	8,45
				8,56
			8,66	8,66
				8,76
			8,87	8,87
				8,98
			9,09	9,09
				9,20
			9,31	9,31
				9,42
			9,53	9,53
				9,65
			9,76	9,76
				9,88

$R_{ном} = (\text{значение из ряда}) \times 10^n$, где n – целое число